

ENGINEERED FALL PROTECTION SYSTEM



PATENT PENDING

WARNING

**DO NOT
ALTER HANDRAIL**

DO NOT EXCEED 3.6m RAIL SPAN BETWEEN POSTS

IMPORTANT: ENSURE RAIL CLAMPS ARE IN THE
LOCKED POSITION AT ALL TIMES



UN-LOCKED

LOCKED

BUILDSAFE

Safety doesn't happen by accident

VIC: 1800 830 266 QLD: 1300 558 027

www.buildsafe.net.au

TESTED AND APPROVED - EXCEEDS AS/NZS 4994.1